

Sensors

Proximity, Photoelectric, and Ultrasonic Sensors, Limit Switches, Pressure Sensors, Machine Safety, Encoders, RFID, and Machine Cabling



Index

Numerics									
2358C	6/203	9007JKC	6/203	L		XCC3510PS48	9/27	XCKT	6/32, 6/33, 6/46 to 6/53
31032-488-01	6/195	9007K	6/203	L100	6/241 to 6/253	XCC3510PS84S●N	9/27		
31032-815-01	6/195	9007KC	6/203			XCC3510PS84CB	9/42	XCKZ	6/88
9007●A	6/204 to 6/209	9007L	6/203	L140	6/241 to 6/253	XCC3510PV84FB	9/46	XCMD	6/12, to 6/27
9007A	6/203	9007N	6/203			XCC3514TS84●●	9/27	XCMN	6/28 to 6/31
9007AB	6/170 to 6/172	9007R	6/203	L2153	6/241 to 6/253	XCC3515CS84CB	9/42	XCMZ	6/27, 6/52
9007AC	6/170 to 6/172	9007T5	6/203			XCC3515CV84FB	9/46	XCNR	6/70 to 6/74
9007AO	6/170 to 6/172	9007T10	6/203	L300	6/241 to 6/253	XCC39	9/29	XCNT2	6/66, 6/67, 6/69
9007AP	6/170 to 6/172	9007ML	6/173 to 6/177	L529	6/241 to 6/253	XCCPM231	9/33	XCNTR	6/70 to 6/75
9007AW	6/170 to 6/172, 6/178	9007MS	6/173 to 6/177			XCCR158RDA●●	9/14 to 9/27 and 9/35	XCPR	6/54 to 6/57
9007B	6/203	9007MS	6/173 to 6/177	Q		XCCR290RDP●●	9/17, 9/23, 9/35	XCR	6/136 to 6/139, 6/142
9007BT	6/195	9007S9	6/195	Q99900911	7/74	XCCR358RD●●	9/42, 9/46, 9/48	XCRT	6/136, 6/137, 6/140, 6/141, 6/143
9007C52	6/185 to 6/188	9007T	6/229 to 6/239	S		XCCR390RDP●●	9/29, 9/35	XCRZ	6/139, 6/141 to 6/143, 6/145
9007C54	6/181 to 6/184, 6/190 to 6/192	9007WJ	6/203	SM3●0A●	4/16	XCCRA	9/34	XCSA	6/270
9007C62	6/181 to 6/184, 6/190 to 6/192	9007WK	6/203	SM3●0A●FP	4/21	XCCRAS10●●	9/34, 9/48	XCSB	6/270
9007C66	6/181 to 6/184	9007WKC	6/203	SM3●2A●	4/28	XCCRB●	9/35	XCSB	6/270
9007CB	6/170 to 6/172	9012G●G	8/160, 8/161	SM4●0A●	4/33	XCCRE●●●	9/35	XCSB	6/270
9007CC	6/170 to 6/172	9012G●O	8/160, 8/161	SM4●1A●	4/33	XCCRF●●	9/35, 9/48	XCSB	6/270
9007CO	6/170 to 6/172, 6/202	9012G●R	8/154, 8/156	SM6●0A●	4/16	XCCRG●	9/35	XCSB	6/270
9007CP	6/170 to 6/172	9012G●W	8/153, 8/155, 8/157, 8/158	SM6●2A●	4/28	XCCRM23SUB37●●	9/33	XCSB	6/270
9007CR	6/222 to 6/225	9016G	8/162	SM6●6A●	4/24	XCCRX●●	9/33	XCSB	6/270
9007CT	6/195, 6/202	9016GVG	8/163	SM8●0A●	4/33	XCDR	6/54, 6/55, 6/58 6/59	XCSB	6/270
9007D	6/203	9049A26S	8/159	SM8●1A●	4/33	XCKD2	6/40, 6/41, 6/44, 6/45, 6/52	XCSB	6/270
9007E	6/203	9998PC	8/166	SM9●0A●	4/16	XCKP	6/32, to 6/39	XCSB	6/270
9007ED	6/203	A		SM9●2A●	4/28	XCKJ	6/102 to 6/129	XCSB	6/270
9007F	6/203	AB1FU10135U	3/112 and 5/159	SM9●6A●	4/24	XCKL	6/76, 6/77, 6/80, 6/81	XCSB	6/270
9007FT	6/229 to 6/239	AB1R11	6/88	T		XCKM1	6/78	XCSB	6/270
9007G	6/203	ABE9	11/38	TCS	10/12, 10/14, 10/15	XCKM5	6/78	XCSB	6/270
9007GD	6/203	ABL8MEM24●●	10/14	TSX	10/14, 10/15	XCKML	6/76, 6/77, 6/82, 6/83	XCSB	6/270
9007H	6/203	ABL8RPS	7/40	V		XCKMR54	6/144, 6/145	XCSB	6/270
9007J	6/203	B		VM1●	4/21, 4/24, 4/28	XCKN	6/62 to 6/65	XCSB	6/270
		BH205	6/195	VM18●	4/16, 4/24, 4/28	XCKP	6/34 6/39, 6/48 6/52	XCSB	6/270
		D		X		XCKQ	6/34 6/39, 6/48 6/52	XCSB	6/270
		DE9RA1012	6/51, 6/52, 6/61	XALZ09	6/52	XCKR	6/92 to 6/101	XCSB	6/270
		DE9RA13520	6/139, 6/141, 6/285, 6/286	XBTZGM128	10/13			XCSB	6/270
		DE9RA1016	2/279, 2/297	XC01●L2	1/166			XCSB	6/270
		DE9RA●●●●	1/285, 1/286	XC1AC	6/150, 6/151			XCSB	6/270
		DIA4ED3051001	10/13	XCC1406	9/10, 9/11, 9/18			XCSB	6/270
		DL1AA	7/73	XCC1506PS	9/13			XCSB	6/270
		F		XCC1510PSM	9/15			XCSB	6/270
		FTX	10/15, 11/40, 11/41, 11/42	XCC1510PS	9/13			XCSB	6/270
				XCC1514TSM	9/15			XCSB	6/270
				XCC1514TS	9/14			XCSB	6/270
				XCC19	9/17			XCSB	6/270
				XCC25	9/21			XCSB	6/270
				XCC29	9/23			XCSB	6/270
				XCC3506	9/27			XCSB	6/270

Index

XCSP3	6/258, 6/259, 6/262, 6/263	XEP5P	6/146, 6/147	XMLCS1	8/115,	XMLG400	8/19, 8/23	XS1N12PA349●	2/54
		XESP2	6/77, 6/103, 6/118, 6/126, 6/129, 6/129, 7/74	XMLCS2	8/119	XMLGM01	8/16, 8/20	XS1N12PB349●	2/54
XCSPA	6/268, 6/269, 6/278 to 6/281			XMLCS3	8/99	XMLGZ001	8/24	XS1N12PC410●	2/58
XCSPL	6/264 to 6/267	XESP2151	7/74	XMLD001	8/104	XMLK0	8/28, 8/29	XS1N18NA349●	2/54
XCSPR	6/264 to 6/267	XESP3021	6/93, 6/99	XMLD002	8/108	XMLK1	8/30, 8/31	XS1N18NB349●	2/54
XCSTA	6/268, 6/269	XGCS	10/12	XMLD004	8/112	XMLK2	8/30, 8/31	XS1N18NC410●	2/58
XCSTE	6/282, 6/283, 6/296 to 6/299	XGFEC	10/13	XMLD010	8/116	XMLK3	8/30, 8/31	XS1N18PA349●	2/54
XCSTL	6/264 to 6/267	XGH	10/12	XMLD020	8/120	XMLZ	8/64, 8/141	XS1N18PB349●	2/54
XCSTR	6/264 to 6/267	XGSTP	10/13	XMLD035	8/124	XPSCM	7/50	XS1N18PC410●	2/58
XCSZ0	6/270 to 6/272	XGSZ0	10/15	XMLD070	8/128	XPSCM1	7/14, 7/24	XS1N30NA349●	2/54
XCSZ1	6/278 to 6/280 and 6/296 to 6/298	XGSZ24	10/15	XMLD160	8/132	XS106B3	2/20	XS1N30NB349	2/54
		XGSZ33PDP	10/12	XMLD300	8/136	XS106BL	2/24	XS1N30NB349D	2/54
		XGSZ3P	10/15	XMLD500	8/140	XS108B3	2/20	XS1N30NC410●	2/58
		XGSZCNF01	10/13	XMLDL35	8/100	XS108BL	2/24	XS1N30PA349●	2/54
		XMLA001	8/101	XMLDM02	8/92	XS112B3	2/20	XS1N30PB349●	2/58
		XMLA002	8/105	XMLE001U1	8/68, 8/72	XS112BL	2/24	XS1N30PC410●	2/58
		XMLA004	8/109	XMLE010U1	8/69, 8/73	XS118B3	2/20	XS208	2/28
		XMLA010	8/113	XMLE025U1	8/69, 8/73	XS118BL	2/25	XS212AA	2/66
		XMLA020	8/117	XMLE060U1	8/70, 8/74	XS130B3	2/20	XS212AL	2/62
		XMLA035	8/121	XMLE100U1	8/70, 8/74	XS130BL	2/25	XS212BL	2/64
		XMLA070	8/125	XMLE250U1	8/71, 8/75	XS1L04N	2/32	XS212SA	2/86
		XMLA160	8/129	XMLE600U1	8/71, 8/75	XS1L04P	2/32	XS218AA	2/66
		XMLA300	8/133	XMLEM01U1	8/68, 8/72	XS1L06N	2/54	XS218AL	2/28
		XMLA500	8/137	XMLEZ	8/76	XS1L06PC410	2/58	XS218BL	2/25
		XMLAM01	8/141, 8/143	XMLF001	8/40, 8/41	XS1L06P	2/58	XS218SA	2/62, 2/64
		XMLB001	8/102	XMLF002	8/42, 8/43	XS1M08NC410●	2/58	XS230AA	2/66
		XMLB002	8/106	XMLF010	8/44, 8/45	XS1M08PC410●	2/58	XS230AL	2/28
		XMLB004	8/110	XMLF016	8/46, 8/47	XS1M12AB120	2/97	XS230BL	2/25
		XMLB010	8/114	XMLF025	8/48, 8/49	XS1M12KP340●	2/60	XS230SA	2/62, 2/64
		XMLB020	8/118	XMLF040	8/50, 8/51	XS1M12MA250●	2/56	XS2L06N●340●	2/32
		XMLB035	8/122	XMLF070	8/52, 8/53	XS1M12MB250●	2/56	XS2L06P●340●	2/32
		XMLB070	8/126	XMLF100	8/54, 8/55	XS1M12PAW01D	2/110	XS2L2SANA	2/62
XCSZ29	6/274	XMLB160	8/130	XMLF160	8/56, 8/57	XS1M18AB120	2/98	XS2L2SAPA	2/62
XCSZ3	6/271, 6/293	XMLB300	8/134	XMLF250	8/58, 8/59	XS1M18KPM40●	2/104	XS2M08NC410●	2/58
XCSZ43	6/285	XMLB500	8/138	XMLF400	8/60, 8/61	XS1M18KP340●	2/60	XS2M08PC410●	2/58
XCSZ8	6/274 to 6/276	XMLBL05	8/142	XMLF600	8/62, 8/63	XS1M18KPM40●	2/104	XS2M12KP340●	2/60
		XMLBL35	8/97	XMLF100	8/54, 8/55	XS1M18MA250●	2/56	XS2M12MA250K	2/56
		XMLBM02	8/90	XMLF160	8/56, 8/57	XS1M18MB250●	2/56	XS2M12MA250●	2/56
XCSZ9	6/271, 6/278, 6/285, 6/296	XMLBM03	8/93	XMLF250	8/58, 8/59	XS1M18MB250●	2/56	XS2M12MB250●	2/56
		XMLBM05	8/95	XMLF400	8/60, 8/61	XS1M18PAS●0	2/108	XS2M12PAW01D	2/111
		XMLBS02	8/106	XMLF600	8/62, 8/63	XS1M18PAW01D	2/110	XS2M18KP340●	2/60
		XMLBS04	8/110	XMLF100	8/54, 8/55	XS1M30KP340●	2/60	XS2M18MA250●	2/56
XCSZ●●	6/296	XMLBS10	8/114	XMLF160	8/56, 8/57	XS1M30KP340●	2/60	XS2M18MB250●	2/56
XCTR	6/54, 6/55, 6/60, 6/61	XMLBS20	8/118	XMLF250	8/58, 8/59	XS1M30MB250●	2/56	XS2M30KP340●	2/60
		XMLBS35	8/97	XMLF400	8/60, 8/61	XS1M30PAW01D	2/109	XS2M30MA250●	2/56
		XMLC001	8/103	XMLF600	8/62, 8/63	XS1N05NA310●	2/32	XS2M30MB250●	2/56
XE2	6/53, 6/88, 6/99, 6/118, 6/126, 6/129	XMLC002	8/107	XMLF100	8/54, 8/55	XS1N05NB310●	2/32	XS2N12NC410●	2/58
		XMLC004	8/111	XMLF160	8/56, 8/57	XS1N05NB311●	2/32	XS2N12PC410●	2/58
		XMLC010	8/115	XMLF250	8/58, 8/59	XS1N05PA310	2/32	XS2N18NC410●	2/58
		XMLC020	8/119	XMLF400	8/60, 8/61	XS1N05PA311●	2/32	XS2N30NC410●	2/58
		XMLC035	8/123	XMLF600	8/62, 8/63	XS1N05PB310	2/32	XS2N30PC410●	2/58
XE3	6/53, 6/88, 6/99, 6/118, 6/126, 6/129	XMLC070	8/127	XMLG001	8/16, 8/20	XS1N05PB311●	2/32	XS4P08MA230●	2/30
		XMLC160	8/131	XMLG006	8/16	XS1N08NA349●	2/54	XS4P08MB230●	2/30
		XMLC300	8/135	XMLG010	8/17, 8/21	XS1N08NB349●	2/54	XS4P08N●3●0	2/30
		XMLC500	8/139	XMLG016	8/17	XS1N08PA349●	2/54	XS4P08P●3●0	2/30
XEP3S	6/148, 6/149	XMLCCL35	8/99	XMLG025	8/17, 8/21	XS1N08PB349●	2/54	XS4P12AB1●0	2/97
		XMLCM02	8/91	XMLG100	8/18, 8/22	XS1N12NA349●	2/54	XS4P12KP340●	2/60
XEP4E	6/146, 6/147, 6/152	XMLCM05	8/96	XMLG250	8/18, 8/22	XS1N12NB349●	2/54	XS4P12M●230●	2/30
		XMLCS0	8/107, 8/111			XS1N12NC410●	2/58		

Index

XT118B1●●●●	3/8	XUB2BNB●M12R	5/32	XUFN353●1	5/118	XUM2BKCNL2T	5/62	XUX8ARCTT16	5/90
XT130B1●●●●	3/8	XUB2BPA●M12R	5/32	XUFN5L0●L2	5/122	XUM2BNANL2●	5/62	XUX9ANAN●●●	5/88
XT132B1●●●●	3/8	XUB2BPB●M12R	5/32	XUFN5P01L●●	5/121	XUM2BNBNL2●	5/62	XUX9ANBN●●●	5/88
XT218A1●●●●●	3/12	XUB4ANA●M12	5/30	XUFN5S01L●●	5/121	XUM2BPANL2●	5/62	XUX9APAN●●●	5/88
XT230A1●●●●●	3/12	XUB4ANB●M12	5/30	XUFS●●20	5/124	XUM2BPBNL2●	5/62	XUX9APBN●●●	5/88
XT232A1●●●●●	3/12	XUB4APA●M12	5/30	XUFZ1●	5/132	XUM5ANCN●●	5/58	XUX9ARCNT16	5/88
XT7C40●●●●●	3/16	XUB4APB●M12	5/30	XUFZ9●●	5/123	XUM5APCN●●	5/58	XUY1111	5/104
XTAZ30	2/131	XUB4BNA●M12	5/32	XUJK803538	5/102	XUM5BN●NL2	5/62	XUYA005●●	5/116, 5/130
XU1N18NP341●●	5/40	XUB4BNB●M12	5/32	XUJZ01	5/153	XUM5BP●NL2	5/62	XUYA110	5/130
XU1N18PP341●●	5/40	XUB4BPA●M12	5/32	XUK0AKSAL2●	5/66	XUM9ANCN●●	5/58	XUYA21●	5/130
XU2M18AP20D	5/48	XUB4BPB●M12	5/32	XUK0AKSAM12●	5/66	XUM9APCN●●	5/58	XUYA220	5/131
XU2M18MA230●●	5/50	XUB5ANA●M12	5/30	XUK0ARCTL2●	5/66	XUM9BN●NL2	5/62	XUYA310	5/131
XU2M18MB230●●	5/50	XUB5ANB●M12	5/30	XUK1ANAN●●●	5/68	XUM9BP●NL2	5/62	XUYA005	5/131
XU2N18NP341●●	5/40	XUB5APA●M12	5/30	XUK1ANBN●●●	5/68	XUMW1KSNL2	5/108	XUYAFLC0966S	5/116
XU2N18PP341●●	5/40	XUB5APB●M12	5/30	XUK1APAN●●●	5/68	XURC3●PML2	5/80	XUYAFP9●●●	5/112
XU2S	7/51	XUB5BNA●M12	5/32	XUK1APBN●●●	5/68	XURC4●PML2	5/80	XUYAFPC0946S	5/112
XU5M18AB20D	5/46	XUB5BNB●M12	5/32	XUK1ARCN●●●	5/68	XURK1KSMM12	5/78	XUYAFPC09●6S	5/112
XU5M18MA230●●	5/50	XUB5BPA●M12	5/32	XUK2AKSN●●●●	5/68	XURZ0●	5/153	XUYAFV9●6S	5/112
XU5M18MB230●●	5/50	XUB5BPB●M12	5/32	XUK2ANAN●●●●	5/68	XUSLAT1	7/40	XUYAFVCO9●6S	5/112
XU5M18U1D	5/34	XUB9ANA●M12	5/30	XUK2ANBN●●●●	5/68	XUSLB	7/10, 7/20	XUYB952●	5/106
XU5N18NP341●●	5/40	XUB9ANB●M12	5/30	XUK2APAN●●●●	5/68	XPSLCM	7/14	XUYB989S●	5/104
XU5N18PP341●●	5/40	XUB9APA●M12	5/30	XUK2APBN●●●●	5/68	XUSLDM	7/11, 7/13, 7/21	XUYBCO989SN	5/104
XU8M18MA230●●	5/50	XUB9APB●M12	5/30	XUK2ARCNL2●	5/68	XUSLN	7/37	XUYBCO989SP	5/104
XU8M18MB230●●	5/50	XUB9BNA●M12	5/32	XUK5ANAN●●●	5/68	XUSLP	7/29 to 7/30	XUYDCFCO966S	5/114
XU9N18NP341●●	5/40	XUB9BNB●M12	5/32	XUK5ANBN●●●	5/68	XUSLZ	7/14, 7/15, 7/31, 7/37	XUYE989	5/104
XU9N18PP341●●	5/40	XUB9BPA●M12	5/32	XUK5APAN●●●	5/68	XUSLZ500	6/318	XUYFA98300●COS	5/104
XUAH0203	5/52	XUB9BPB●M12	5/32	XUK5APBN●●●	5/68	XUSZ	7/40	XUYECO989	5/104
XUAH0●●●●	5/52	XUBLAKCN●●●●	5/44	XUK5ARCNL2	5/68	XUVA0505PANM8	5/135	XUYFPDC●●●●	5/114
XUAJ0●●●●	5/52	XUBLANCNL2●	5/44	XUK8AKSN●●●	5/70	XUVF●●●●●●	5/149	XUYFP2BRINA005B	5/131
XUB0AKSN●●●●	5/28	XUBLANCNM12●	5/44	XUK9ANAN●●●	5/68	XUVH0312	5/147	XUYFVERM●61	5/127, 5/128
XUB0AKSW●●●●	5/28	XUBLAPCNL2●	5/44	XUK9ANBN●●●	5/68	XUVJ0312	5/147	XUYFVERT●61	5/127, 5/128
XUB0ANSN●●●●	5/28	XUBLAPCNM12●	5/44	XUK9APAN●●●	5/68	XUVK0252●S	5/143	XUYFVPM●61	5/125
XUB0ANSW●●●●	5/28	XUBLBKCNC●●●●	5/44	XUK9APBN●●●	5/68	XUVR06●●●●●M8	5/135	XUYFVPS●61	5/125
XUB0APSN●●●●	5/28	XUBLBNCNL2●	5/44	XUK9ARCNL2	5/68	XUVR12●●●●●M8	5/135	XUYFVPT●61	5/125
XUB0APSW●●●●	5/28	XUBLBNCNM12●	5/44	XUKC1●SMM12	5/76	XUVU06M3KCNM8	5/145	XUYP95●●	5/106
XUB0BKSNL●●●	5/28	XUBLBPCNL2●	5/44	XUKR1●SMM12	5/74	XUX0AKSA●●●●	5/86, 5/88	XUYP989S●	5/104
XUB0BKSW●●●●	5/28	XUBLBPCNM12●	5/44	XUKT1KSM●●●	5/72	XUX0ARCTT16●	5/86, 5/88	XUYPCO989S●	5/104
XUB0BKSW●●●●	5/28	XUBT1NSN●●●●	5/36	XULA040119●	5/97	XUX1ANAN●●●●	5/88	XUYPS1LCO966S	5/82
XUB0BNSN●●●●	5/28	XUBT1PSN●●●●	5/36	XULA040219●	5/97	XUX1ANBN●●●●	5/88	XUYPS2945S	5/84
XUB0BNSW●●●●	5/28	XUBTANSN●●●●	5/36	XULA06011●	5/97	XUX1APBN●●●●	5/88	XUYPS2CO945S	5/84
XUB0BPSN●●●●	5/28	XUBTANSW●●●●	5/36	XULA06021●	5/97	XUX1APBNT16	5/88	XUYPS989S●	5/104
XUB0BPSW●●●●	5/28	XUBTAPSN●●●●	5/36	XULA700115●	5/97	XUX1ARCNT16	5/88	XUYR989S●	5/104
XUB0SKSN●●●●	5/38	XUBTAPSW●●●●	5/36	XULA700215●	5/97	XUX1ARCNT16	5/88	XUYRCO989S●	5/104
XUB0SKSN●●●●	5/38	XUBTSNSN●●●●	5/36	XULH043539●	5/96	XUX2ANAN●●●●	5/88	XUZ200●	5/151
XUB0SKSW●●●●	5/38	XUBTSNSW●●●●	5/36	XULH06353●	5/96	XUX2ANBN●●●●	5/88	XUZK2000	5/75, 5/77
XUB0SNSN●●●●	5/38	XUBTSPSN●●●●	5/36	XULH083534●	5/96	XUX2APAN●●●●	5/88	XUZ2003	5/28 to 5/155, 6/10
XUB0SNSW●●●●	5/38	XUBTSPSW●●●●	5/36	XULH703535●	5/96	XUX2APBNM12R	5/88	to	
XUB0SPSN●●●●	5/38	XUC2AKSA●●●●	5/92	XULJ043539●	5/96	XUX2AP●NT16R	5/88	to	
XUB0SPSW●●●●	5/38	XUC8AKSN●●●●	5/92	XULJ06353●	5/96	XUX2ARCNT16R	5/88	to	
XUB1ANA●●●●●	5/30	XUC9AKSA●●●●	5/92	XULJ083534●	5/96	XUX5ANAN●●●●	5/88	6/24	
XUB1ANB●●●●●	5/30	XUDA1NSM●●	5/110	XULJ083534●	5/96	XUX5ANBN●●●●	5/88		
XUB1APA●●●●●	5/30	XUDA1PSM●●	5/110	XULJ703535●	5/96	XUX5APAN●●●●	5/88		
XUB1APB●●●●●	5/30	XUDA2NSM●●	5/110	XULK0830●	5/96	XUX5APBNM12	5/88		
XUB1BNA●●●●●	5/32	XUDA2PSM●●	5/110	XULM040319	5/100	XUX5APBNT16	5/88		
XUB1BNB●●●●●	5/32	XUFN013●1	5/121	XULM060●●	5/100	XUX5ARCNT16	5/88		
XUB1BPA●●●●●	5/32	XUFN02323	5/121	XULM0803●●	5/100	XUX8AKSA●●●●	5/90		
XUB1BPB●●●●●	5/32	XUFN04331	5/121	XULZ41	5/151				
XUB2AKS●●●●●	5/30	XUFN05321●●●	5/120	XUM0AKSA●●T	5/56				
XUB2ANA●M12R	5/30	XUFN053●●	5/120	XUM0ANSA●●	5/56				
XUB2ANB●M12R	5/30	XUFN12301●●●	5/118	XUM0APSA●●	5/56				
XUB2APA●M12R	5/30	XUFN12311	5/118	XUM2AKCN●●●	5/58				
XUB2APB●M12R	5/30	XUFN2L01L●●	5/119	XUM2AKCN●●●	5/58				
XUB2BKS●M12T	5/32	XUFN2P01L●●	5/119	XUM2ANCN●●●	5/58				
XUB2BNA●M12R	5/32	XUFN2S01L●●	5/119	XUM2ANCN●●●	5/58				

Index

XUZA218	5/28 to 5/155	XXZPB100	4/16, 4/21, 4/24, 4/28	XZCP1241L	6/306, 8/24, 8/32, 8/64, 6/16 to 6/24 and 9/10	Z		ZCKZ0	6/119
XUZA318	5/28 to 5/155	XY2CE	7/71			ZA2B	7/74	ZCMC21E	6/26
XUZA4●	5/151	XY2CH	7/72			ZC1A	6/134	ZCMC25T06	6/26
XUZA50	5/28 to 5/155	XY2CZ	7/73,			ZCD	6/40, to 6/50	ZCMD	6/14 to 6/27
XUZA51	5/28 to 5/155	XZCB4L	11/37	XZCP1264L	6/20, 6/108, 8/76, 11/11	ZCE01	6/15, 6/19, 6/35 to 6/49	ZCP	6/20, 6/34 to 6/39, 6/50
XUZAM0●	5/58	XZCC8F	6/10, 9/26, 9/27			ZCE02	6/14, 6/18, 6/34 to 6/46	ZCT2	6/46, 6/47, 6/51
XUZAM81	5/62	XZCC12FC	6/10 to 6/28, 11/28,	XZCP1340L	11/10			ZCY	6/15, 6/19, 6/35, 6/39, 6/41, 6/45, 6/47
XUZB0●	5/153		11/29	XZCP1440L	11/10				
XUZB1●	5/153	XZCC12FD	11/28, 11/29	XZCP1541L	11/11	ZCE05	6/27, 6/52		
XUZB2003	55/28 to 5/155, 6/10, 6/24	XZCC12FDB50R	11/29	XZCP1564L	11/11	ZCE06	6/15, 6/19, 6/35 to 6/46	ZEP3L5	6/148
XUZB2005	3/62, 5/38, 5/151	XZCC12FDM40B	6/10 to 6/28 and 11/28	XZCP1662L	11/13			ZEP4L	6/148
XUZB32	2/131	XZCC12FDP40B	6/10 to 6/24 and 11/28	XZCP1670L	11/13	ZCE10	6/14, 6/18, 6/34 to 6/46		
XUZC08	55/28 to 5/155		6/24 and 11/28	XZCP1764L	8/64, 11/13				
XUZC100	5/153	XZCC12M	11/30, 11/31	XZCP1771L	6/20, 6/108, 11/13	ZCE11	6/14, 6/18, 6/34 to 6/46		
XUZC16	5/153	XZCC18F	11/32	XZCP1865L	11/12				
XUZC2●	5/153	XZCC20F	11/29	XZCP1965L	11/12				
XUZC3●	5/153	XZCC20M	11/31	XZCP2540L	11/10	ZCE21	6/34 to 6/46		
XUZC50	55/28 to 5/155	XZCC23F	11/34	XZCP2737L	11/9				
XUZC50HP	5/36	XZCC23M	11/35	XZCP29P11L	6/306	ZCE24	6/14, 6/18		
XUZC80	5/153	XZCC43F	11/33	XZCP29P12L	6/318	ZCE27	6/34, 6/38 to 6/44		
XUZD●5	5/153	XZCE	11/36	XZCPA	11/22, 11/23				
XUZE0●	2/131, 5/153	XZCG0223	11/37	XZCR15	11/18 to 11/21	ZCE28	6/34, 6/38 to 6/44		
XUZK2003	55/28 to 5/155	XZCP0166L	11/8	XZCR27	11/14, 11/15	ZCE2F	6/14 6/18		
XUZK2004	55/28 to 5/155	XZCP0266L	11/8	XZCRA	11/24, 11/25	ZCEG1	6/14 6/18		
XUZMSH●●	5/58	XZCP0366L	11/8	XZLG10	11/37	ZCEH	6/35, 6/39 to 6/47		
XUZMSV●●	5/58	XZCP0466L	11/8	XZCC12FDM40B	8/24, 8/32	ZCKD	6/78, 6/80, 6/94		
XUZMU01	5/58	XZCP0566L	11/9	XZCC23FDP1	9/33	ZCKE	6/104, 6/125, 6/128, 6/129		
XUZM20●●	5/56, 5/151	XZCP0666L	11/9	XZCC23FMDP120S	9/33	ZCKJ	6/104 to 6/129		
XUZX200●	5/86, 5/88, 5/151	XZCP0766L	11/9	XZCCHFDM370S	9/33	ZCKL	6/80, to 6/87		
XX2D●	4/28	XZCP0866L	11/9	XZCP0566L●	5/135	ZCKM	6/78, 6/86, 6/87		
XX2V3●	4/28	XZCP0941L	6/306, 11/9	XZCP0941L●●	5/84, 5/112, 5/114, 5/116, 5/100, 5/137	ZCKS	6/94, 6/98		
XX6V3●	4/16	XZCP0●66L2	6/10			ZCKY	6/104, 6/126, 6/129		
XX8D●	4/21	XZCP1041L	5/68, 5/74, 5/112, 6/306, 11/9	XZCP1041L●	5/84, 5/112, 5/114, 5/116, 5/100, 5/137				
XX9D●	4/24		5/68, 5/74, 5/112, 6/306, 11/9						
XX9V3●	4/24	XZCP1141L	6/16 to 6/24, 6/306, 8/32, 8/64, 11/10	XZCP1141L●	5/110				
XXZ12●	4/12		6/20, 6/108, 8/76, 11/11	XZCP1164L●	5/110				
XXZ1933	4/21	XZCP1164L	6/20, 6/108, 8/76, 11/11	XZCPA1141L●●	2/62, 2/66				
XXZ30●	4/16, 4/21, 4/24, 4/28		6/20, 6/108, 8/76, 11/11	XZCPA1241L●●	2/62, 2/66				
		XZCP1169L	6/20, 11/11	XZCPA1865L●●	2/62, 2/66				
				XZCPA1965L●●	2/62, 2/66				
				XZCRA151140A●	2/62, 2/66				

Schneider Electric USA, Inc.

www.SeSensors.com

**Schneider Electric Sensor
Competency Center**
1875 Founders Drive
Dayton OH 45420
(800) 435-2121

The information and dimensions in this catalog are provided for the convenience of our customers. While this information is believed to be accurate, Schneider Electric reserves the right to make updates and changes without prior notification and assumes no liability for any errors or omissions.

**Schneider Electric Canada,
Inc.**
5985 McLaughlin Road
Mississauga, Ontario L5R 1B8
(800) 435-2121

Design: Schneider Electric
Photos: Schneider Electric

© 2010 Schneider Electric. All Rights Reserved.

November 2010

9006CT1007