



**Discontinued Parts from the Disconnect Switch Line and Replacement Parts**

**16-100A Fusible and Non-Fusible Disconnect Switches & Accessories**

| Discontinued Part Number | Discontinued EAN/UPC | Replacement Part Number | Replacement EAN/UPC |
|--------------------------|----------------------|-------------------------|---------------------|
| BDH104                   | 051712581219         | BDH56                   | 051712581851        |
| BDH105                   | 051712581233         | BDH57                   | 051712412001        |
| BDH106                   | 5027590147507        | BDH58                   | 051712581288        |
| BDH106SS                 | 051712541442         | BDH58SS                 | 051712238847        |
| BDH106SH                 | 051712666442         | BDH58SH                 | 051712238830        |
| BDH106T                  |                      | BDH58T                  | 051712238854        |
| BDH107                   | 5027590153133        | BDH59                   | 051712581295        |
| BDH107T                  |                      | BDH59T                  | 051712238878        |
| BDH107SH                 | 051712666459         | BDH59SH                 | 051712238861        |
| CDHXB65                  | 5027590241090        | CDHXB65L6               | 051712239523        |
| CDHXY65                  | 5027590211840        | CDHXY65L6               | 051712239530        |
| CDS48P                   | 5027590241137        | BDS150                  | 051712412247        |
| CDS49P                   | 051712286428         | BDS265                  | 051712412308        |
| CDS50P                   | 051712286435         | BDS400                  | 051712412285        |
| CDS67P                   | 5027590147514        | BDS170                  | 051712412353        |
| CDS99P                   | 5027590227896        | BDS500                  | 051712412452        |
| BDH79                    | 5027590163095        | BDHA79                  | 051712238885        |
| CDH7S                    | 051712286237         | CBDH7S                  | 051712239356        |
| CDH8S                    | 051712286244         | CBDH8S                  | 051712239363        |
| CDH9S                    | 051712286251         | CBDH9S                  | 051712239370        |
| CDH19S                   | 051712581509         | CBDH19S                 | 051712239271        |
| CDH20S                   | 051712581516         | CBDH20S                 | 051712239295        |
| CDH10S                   | 051712286268         | CBDH10S                 | 051712239189        |
| CDH11S                   | 051712579193         | CBDH11S                 | 051712239196        |
| CDH12S                   | 051712579209         | CBDH12S                 | 051712239202        |
| CDH17S                   | 051712581523         | CBDH17S                 | 051712239257        |
| CDH18S                   | 051712581530         | CBDH18S                 | 051712239264        |
| CDH13S                   | 051712579216         | CBDH13S                 | 051712239219        |
| CDH14S                   | 051712579223         | CBDH14S                 | 051712239226        |
| CDNF16D                  | 051712286145         | CDNF16A3D               | 051712239806        |
| CDNF25D                  | 051712286152         | CDNF25A3D               | 051712239875        |
| CDNF32D                  | 051712286169         | CDNF32A3D               | 051712239998        |
| CDNF45D                  | 051712579063         | CDNF45A3D               | 051712240079        |
| CDNF63D                  | 051712579278         | CDNF63A3D               | 051712240192        |
| CDNF30D                  | 051712603669         | CDNF30A3D               | 051712239943        |
| CDNF60D                  | 051712588881         | CDNF60A3D               | 051712240147        |
| CDNF100D                 | 051712318143         | CDNF100A3D              | 051712239714        |
| CDHZX6                   | 051712669566         | CDHZSX6                 | 051712239547        |
| CDH1S                    | 051712286176         | CBDH1S                  | 051712239288        |
| CDH2S                    | 051712286183         | CBDH2S                  | 051712239301        |
| CDH15S                   | 051712579230         | CBDH15S                 | 051712239233        |
| CDH16S                   | 051712579032         | CBDH16S                 | 051712239240        |
| CDH3S                    | 5027590165242        | CBDH3S                  | 051712239318        |
| CDH4S                    | 5027590165259        | CBDH4S                  | 051712239325        |
| CDH5S                    | 051712286213         | CBDH5S                  | 051712239332        |
| CDH6S                    | 051712286220         | CBDH6S                  | 051712239349        |
| CDNF16                   | 5027590165273        | CDNF16A3                | 051712239790        |
| CDNF25                   | 051712286114         | CDNF25A3                | 051712239868        |

5mm to 6mm Discontinuance List with UPC's, 9/4/09

|           |               |            |              |
|-----------|---------------|------------|--------------|
| CDNF32    | 5027590097680 | CDNF32A3   | 051712239981 |
| CDNF45    | 5027590241106 | CDNF45A3   | 051712240062 |
| CDNF63    | 5027590241113 | CDNF63A3   | 051712240185 |
| CDNF30    | 051712615617  | CDNF30A3   | 051712239936 |
| CDNF60    | 051712615624  | CDNF60A3   | 051712240130 |
| CDNF100   | 5027590165266 | CDNF100A3  | 051712239707 |
| CDS85S    | 5027590147484 | BDS85S     | 051712239042 |
| CDS105S   | 5027590241120 | BDS105S    | 051712238960 |
| CDS120S   | 051712286350  | BDS120S    | 051712238977 |
| CDS130S   | 051712286367  | BDS130S    | 051712238984 |
| CDS180S   | 5027590165280 | BDS180S    | 051712239004 |
| CDS250S   | 051712286381  | BDS250S    | 051712239011 |
| CDS330S   | 051712286398  | BDS330S    | 051712239028 |
| CDS32P    | 5027590147477 | CDS32PP    | 051712240314 |
| CDS63P    | 051712286497  | CDS63PP    | 051712240352 |
| CDS125P   | 051712579094  | CDS125PP   | 051712240291 |
| CDL32P    | 051712286503  | CDL32PP    | 051712239585 |
| CDL63P    | 051712581561  | CDL63PP    | 051712239615 |
| CDL125P   | 051712579049  | CDL125PP   | 051712239561 |
| CDN32P    | 051712286565  | CDN32TP    | 051712239660 |
| CDN63P    | 051712581455  | CDN63TP    | 051712239691 |
| CDN125P   | 051712579285  | CDN125TP   | 051712239646 |
| CDD32P    | 051712286589  | CDD32TP    | 051712239417 |
| CDD63P    |               | CDD63TP    | 051712239431 |
| CDD125P   |               | CDD125TP   | 051712239400 |
| CDE32P    | 051712286602  | CDE32TP    | 051712239479 |
| CDE63P    |               | CDE63TP    | 051712239516 |
| CDE125P   | 051712579179  | CDE125TP   | 051712239455 |
| CDTS32T3  | 051712286527  | CDTS32AT3  | 051712240390 |
| CDTS63T3  | 051712286534  | CDTS63AT3  | 051712240413 |
| CDTS32T1  | 051712286541  | CDTS32AT1  | 051712240383 |
| CDTS63T1  |               | CDTS63AT1  | 051712240406 |
| CDTS125T3 | 51712579308   | CDTS100T3  | 051712636537 |
| CDTS125T1 | 51712579292   | CDTS100T1  | 051712240376 |
| CFD30J3   | 5027590241168 | CFD30AJ3   | 051712240475 |
| CFD30CC3  | 051712609500  | CFD30ACC3  | 051712240437 |
| CFD30J4   | 051712609531  | CFD30AJ4   | 051712240505 |
| CFD30CC4  | 051712609517  | CFD30ACC4  | 051712240468 |
| CFD30J3S  | 5027590147521 | CFD30AJ3S  | 051712240499 |
| CFD30CC3S | 051712675710  | CFD30ACC3S | 051712240451 |
| CFD30J3F  | 5027590241175 | CFD30AJ3F  | 051712240482 |
| CFD30CC3F | 051712587471  | CFD30ACC3F | 051712240444 |
| CDZW8     | 051712286626  | CDZW8      | 051712286626 |
| CDZW6     | 051712286633  | BDZW1      | 051712293686 |
| CDZW17    | 051712286640  | CDZW17     | 051712286640 |
| CDS32D    | 051712286480  | CDS32PD    | 051712240307 |
| CDS63D    | 051712581707  | CDS63PD    | 051712240345 |
| CDS100D   | 051712613132  | CDS100PD   | 051712240284 |
| CDL32D    |               | CDL32PD    | 051712239578 |
| CDL63D    |               | CDL63PD    | 051712239608 |
| CDL100D   |               | CDL100PD   | 051712239554 |
| CDN32D    | 051712286572  | CDN32PD    | 051712239653 |
| CDN63D    |               | CDN63PD    | 051712239684 |
| CDN100D   |               | CDN100PD   | 051712239639 |
| CDE32D    | 051712286619  | CDE32PD    | 051712239462 |
| CDE63D    |               | CDE63PD    | 051712239509 |

5mm to 6mm Discontinuance List with UPC's, 9/4/09

|                    |              |                    |              |
|--------------------|--------------|--------------------|--------------|
| <b>CDE100D</b>     |              | <b>CDE100PD</b>    | 051712239448 |
| <b>CDS48T</b>      |              | <b>BDST4</b>       | 051712581332 |
| <b>CDS67T</b>      | 051712581691 | <b>BDST25</b>      | 051712581349 |
| <b>CDS49T</b>      | 051712581677 | <b>BDST29</b>      | 051712581356 |
| <b>CDS50T</b>      |              | <b>BDST30</b>      | 051712581363 |
| <b>OPMRH</b>       | 51712797184  | <b>CDRKBS12</b>    | 051712240253 |
| <b>CDBY68306</b>   | 051712581400 | <b>CDRKBS2</b>     | 051712240260 |
| <b>CDBY68419/1</b> | 51712581417  | <b>CDRKYS2</b>     | 051712240277 |
| <b>CDMC1</b>       | 051712554046 | <b>CDMCS2</b>      | 051712239622 |
| <b>CDSWM5X8</b>    | 051712581721 | <b>CDSWM5X8A</b>   | 051712240369 |
| <b>BDZW5</b>       | 051712293648 | <b>BDZW6</b>       | 051712293655 |
| <b>BDZXB</b>       |              | <b>BDZXB8</b>      | 051712239066 |
| <b>CDNF125</b>     | 051712569743 | <b>CDNF125A3</b>   | 051712239752 |
| <b>BDFLNF30-F</b>  | 051712291637 | <b>BDFLNF30-F</b>  | 051712291637 |
| <b>BDFLNF60-F</b>  | 051712291644 | <b>BDFLNF60-F</b>  | 051712291644 |
| <b>BDFLNF100-F</b> | 051712291651 | <b>BDFLNF100-F</b> | 051712291651 |

